

(3)

New M/R

(N.A.)

FIELD INSPECTION REPORT

Date of Inspection : 15/12/2020	District: BHOPUR
Division : AYA	Length (km): 2.00 km
Name of the Road: Hanuman Garhi Mahuli Gram Se Aya Salawapur Path	
Scheme/Programme: MAINTENANCE	
Package No.: RM/BH/AYA/19/0004	Road Id No.: 1040/604100
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NIL
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

N.A. ✓

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Remarks: STATUS: Ongoing. Edge marking & road furniture's fixation still pending

(Signature) 15/12/20
E.E.

NAME: