

6

N. A

"out of maintenance"

FIELD INSPECTION REPORT

Date of Inspection : 15/12/2020	District: Bhojpur
Division : Ara	Length (km): 3.600 km
Name of the Road: Ara Salempur Road to Daripur	
Scheme/Programme: MAINTENANCE	
Package No.: 13 F 2/2013-14	Road Id No.: 10401608102
Status of the Project: Ongoing/Completed/Under Maintenance	(out of maintenance)
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating : N. A. ✓

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remarks : Status: Out of maintenance.


 15/12/20
 (Signature) EE

NAME: