

FIELD INSPECTION REPORT

Date of Inspection :	15-12-20	District:	Aurangabad.
Division :	Aurangabad	Length (km):	4.368 km
Name of the Road:	Tengra to Rahua.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	☒ Ongoing/Completed/Under Maintenance		
Work is a case of:	☒ New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No NA
g)	Compaction of flank/slope & raincuts if any	✓Yes/No raincuts
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained 200m	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA.

Overall Rating :

☒ Satisfactory (S)	
☐ Satisfactory but requires Improvement (SRI)	
☐ Unsatisfactory (U)	

NAME:


 (Signature)
 E.E.
 Regional Lab
 Gulzarbagat