FIELD INSPECTION REPORT

Date of I	nspection: 13.12.2020 District: Jamui.	24 - 277 - 2
Division :	: R.W.D (W) ygorci Length (km): 6.00 K	ø) ′
Name of	the Road: Bahoalon p.w. D oval to Belda	
Scheme/I	Programme: MAINTENANCE	P.W.Dr
Package	2000-110	5163
Status of	the Project: Ongoing/Completed/Under Maintenance	
Work is		
SI No.	The second of th	Remarks
1	Pavement	
a)	Road Junction condition	√S/U
b)	Condition of Surfacing	s/ų/
c)	Riding Quality	√S/U
d)	Road Camber	√\$/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No .
換劑	Cross Dealinge	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Comiture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
排開	Compliance History	
a)	Status of ATR's & any others	MIA

Overall Rating

	. •
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	(1).

131121 2020

(Signature) A É

NAME:

DESIGNATION: