

FIELD INSPECTION REPORT

Date of Inspection : 15.12.2020	District: Purnea
Division : Baise	Length (km): 1.323
Name of the Road: NH 31 Lal Bahadur Shastri Sah house	
Scheme/Programme: MAINTENANCE	MMGSY
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	SU S
a)	Road Junction condition	SU S
b)	Condition of Surfacing	SU S
c)	Riding Quality	SU S
d)	Road Camber	Yes/No Yes
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	S/SRI/U S
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	S.
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

R. B. Singh
(Signature) 15/12/2020

NAME: R. B. Singh

DESIGNATION: J. E