

FIELD INSPECTION REPORT

Date of Inspection : 14.12.2020

District: Katihar

Division: Bazar

Length (km):

Name of Road: Chayndi Bhullah to chowk to Madhopur chowk

Scheme/Programme: MAINTENANCE

Package No.:

Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of : New Connectivity/Up gradation/Maintenance

Sl NO.	Parameters to be checked	Remarks
--------	--------------------------	---------

1 Payement

a) Road Junction condition

S/U

b) Condition of Surfacing

S/U

c) Riding Quality

S/U

d) Road Camber

S/U

e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.

Yes/No

f) Contraction Joints provided or no (CC Pavement)

Yes/No

g) Compaction of flank/slope & raincuts if any

Yes/No

2 Cross Drainage

a) Condition of head walls in Hume Pipe culverts including its Pinting

S/SRI/U

b) Condition of Abutment & Wing walls, Slab in RCC culverts

S/SRI/U

c) Condition of railings/slab/approach for Bridges

S/SRI/U

3 Road Furniture

a) Wheather sing boards/informatory/cautionary Board/Km & 200m stones/Pavement road markings are provided and Maintained

Yes/No

4 Compliance History

a) Status of ATR's & any other

N/A

Overall Rating :

Satisfactory (S)

"S"

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NAME:

DESIGNATION:

महेश्वर मिश्र
महेश्वर मिश्र

(Signature)

14.12.2020
JE Bazar