

pmusy

# FIELD INSPECTION REPORT

Date of Inspection :	2-12-2020	District:	Kuthuv
Division :	Kuthuv-2	Length (km):	1.462 km
Name of the Road:	L032-To3 to T.P. Thari		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	21205902018
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U S	
b)	Condition of Surfacing	S/U S	
c)	Riding Quality	S/U S	
d)	Road Camber	S/U -U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U -S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U -S	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U -SRI	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

  
(Signature)

NAME:

DESIGNATION: