

FIELD INSPECTION REPORT

pmussy

Date of Inspection : 2-12-2020		District: Kothari
Division : Kymms-2		Length (km): 1-378 km
Name of the Road: L68 - To 5 to Arrabam		
Scheme/Programme: MAINTENANCE ✓		
Package No.:		Road Id No.: 21205902048
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U -S
c)	Riding Quality	S/U S
d)	Road Camber	S/U -S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No -S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U -S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U -SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	←
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Km
2-12-2020
(Signature)

NAME: