FIELD INSPECTION REPORT

Date of l	Inspection:	08/12/20	District: KNE	
Division		-2	Length (km): 2-783	
Name of	the Road;	Nyvi chon	UR SH-63 to Azam	Nagar
Scheme/	Programme:	MAINTENANCE		
Package	No.:		Rond Id No.: 2/ 20591 25	216
Status o	f the Project:	Ongoing/Complete	ed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance Remarks		Demorks
Sl. No.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Parameters t	o be checked	Kemarka
1.	Pavement			S/U/
a)	Road Junction condition			V
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	n 1 Combor			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No/
	aggregates in C	ints provided or not	(CC Pavement)	Yes/No
f)				Yes/No
g)	THE RESERVE OF THE PARTY OF THE	flank/slope & raino	TIME CONTRACTOR	
2	Cross Draina	ge and and a		S/SRI/U
a)	Condition of h	ead walls in Hume	pipe culverts including its painting	
	Condition of A	butment & Wing w	valls, Slab in RCC culverts	S/SRI/U
b)	Condition of railings/slab/approach for Bridges			S/SRI/U
c)	Road Furnitu	3 4 17 8 11 11 11	- 11:11	
a)		boards/informator	y/cautionary Board/km & 200m re provided and maintained	Yes/No
4.	Compliance H	The second secon		
a)		s & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRA
Unsatisfactory (U)	

NAME: B' Marales

(Signature)

Conned by ComConner