

6

FIELD INSPECTION REPORT

Date of Inspection : 16.12.20		District:
Division : R.H.D. Chapra		Length (km): 3.19 km
Name of the Road: B.A.P. from K.D. Dahan to K.D. Dahan		
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sr. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincut if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	N.D.

Overall Rating :

Satisfactory (S)	☒
Satisfactory but requires Improvement (SRI)	☐
Unsatisfactory (U)	☐

NAME:

DESIGNATION:

(Signature) 16.12.20

20/2/21
14/12/2020
A.E.
Banyan