

(10)

FIELD INSPECTION REPORT

Date of Inspection :	16/12/2020	District:	Chapra (G.P.)
Division :	R.W.D. Chapra-2	Length (km):	0.500 Km
Name of the Road:	LP36 to Haspur		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	G.T.S.N. 7
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Remarks
Sl. No.	Parameters to be checked		
1.	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		Yes/No
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
	Contraction Joints provided or not (CC Pavement)		Yes/No
	Compaction of flank/slope & raincut if any		
2.	Cross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)	☒
Satisfactory but requires Improvement (SRI)	☐
Unsatisfactory (U)	☐

NAME: .

DESIGNATION:

(Signature) 16.12.20

4112PY
16/12/20
AE D