

FIELD INSPECTION REPORT

Date of Inspection : 05/12/2020		District: Muzaffarpur
Division : R.W.D. Muzaffarpur East		Length (km): 3.1 km
Name of the Road: NH-28 Bakhari Harpur Se Baskuli Himmat Singh.		
Scheme/Programme: MAINTENANCE (PMUSY)		
Package No.: BR-23R-352		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Some portion of Flank damage due to Flood 2020

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME: Santosh Kumar Panka
DESIGNATION: Junior Engineer

Santosh Kumar Panka
(Signature) 05/12/2020
J.E.
(Bochaha)

Scanned with CamScanner