

FIELD INSPECTION REPORT

Date of Inspection : 11.12.2020	District: muzaffarpur
Division : Muzaffarpur East-2	Length (km): 1.035 km
Name of the Road: Sakinagar PMGSY Sadak to Baidnath nagar kote hore sam cloudary hore	
Scheme/Programme:	MAINTENANCE mmgsy
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No✓
4.	Compliance History	—
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	(U)

Ganesh Kumar -
11/12/2020
(Signature)

NAME: GANESH KUMAR

DESIGNATION: JUNIOR ENGINEER