FIELD INSPECTION REPORT

	spection: 09 12 202			
Division	R. W.D. Muzaterpun	Fath-2 Length (km): 1.885 K.M		
Name of	the Road: NH-57 P.	m. h.s.y Botal chowk to mol	nanburcho	mole.
	rogramme: MAINTEN	Road Id No.:		
Package		ompleted/Under Maintenance		
		ectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked			
1.	Payement			
a)	Road Junction condition	US/tJ		
b)	Condition of Surfacing	S/U	e for a final	
c)	Riding Quality	√S/U		
d)	Road Camber	₩S/U		
c)	Whether free from def aggregates in case of CC I	¥es/No		
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	of Flank
2.	Cross Drainage			
a)	Condition of head walls in	S/SRI/U	of flood	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History		14	
a)	Status of ATR's & any of		1 1	
Overall		of P.c. c & B. T Jamaje Que so ove	w toping at	Hook 202
Overall	Satistac	tory (S)		
	Satisfac	tory but requires Improvement (SRI)		

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	"V"

NAME: Santosh kumor Panjkaj DESIGNATION: Junioy Engineer

Saufosh v. Pankaj (Signature) 09/12/2020 J. E (Bochoha)

Scanned with CamScanner