

# FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020		District: muzaffarpur
Division : R.W.D. Muzaffarpur East		Length (km): 2.615 km
Name of the Road: mmasy - Dular ojaaha house to turki chowk		
Scheme/Programme: MAINTENANCE		(mmasy)
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Some portion of flank damage due to over taking of Floodwater 2020.

Overall Rating :

Some portion of B.T damage due to over taking of Flood 2020.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	

NAME: Santosh Kumar Panka  
DESIGNATION: Junior Engineer

Santosh Kumar Panka  
(Signature) 07/12/2020  
J-E  
(Bochaha)

Scanned with CamScanner