

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>बेदा/बेदा</u>
Division : <u>हाजीपुर</u>	Length (km): <u>1.422</u>
Name of the Road: <u>21/21 गेहूँ पंचायत का.मंडल हाजीपुर लायंग्स पुलव मार्ग से राम किशोर</u>	
Scheme/Programme: <u>MAINTENANCE</u>	<u>सड़क पथ पर सड़क कि. के 1/2 भाग पोखर</u>
Package No.:	Road Id No.:
Status of the Project: ☒ Ongoing/Completed/Under Maintenance ✓	
Work is a case of:	New Connectivity/Up gradation/ Maintenance

सड़क पथ पर सड़क कि. के 1/2 भाग पोखर

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road function condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S) ✓	<u>5</u>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

13/12/20
(Signature) J.E

NAME:

DESIGNATION: