Division	"ISDAAL	IELD INSPECTION	istrict: E. Champo	erb
- O	f the D	L	ength (Km):	and to M
Scheme	Programme:	Lagan Thakur ke	ghar to Gopal Chi	CA ON
Package	No.:	INTENANCE	nom he	
Status o	f the Project : On	R	oad ID No.:	Š.
Norte	the Project : On	Ongoing/Completed/Under Maintenance		
SI. No.	a case of :	w Connectivity/Up Grada	tion/ Maintenance	
1,	Parameters to be checked Remai			Remarks
	Pavement			
a)	Road Junction condition	Road Junction condition		's'
b)	Condition of Surfacing			191
c)	Riding Quality			151
d)	Road Camber			151
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			'S'
f)	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			'S'
2,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			15/
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			_
c)	Condition of railings/slab/approach for Bridges			_
3,	Road Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			151
4,	Compliance History			
	Status of ATR's & any oth			

Overall Rating

Satisfactory (S)	S
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

16.12.2020 J.E

(Signature)

NAME:

DESIGNATION: