

FIELD INSPECTION REPORT

Date of Inspection :	16/12/2020	District:	Nalanda
Division :	Haridwar	Length (km):	0.850 km
Name of the Road:	Kharjariyabigha more (Nalanda) - 5.1 km to Kharjariyabigha		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition S	S/U
b)	Condition of Surfacing U	S/U
c)	Riding Quality U	S/U
d)	Road Camber U	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. NO.	Yes/No
f)	Contraction Joints provided or not (CC Pavement) NO.	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N/A	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained NO.	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	✓

(Signature) 16/12/2020

NAME: RAUL KUMAR

DESIGNATION: Sr. Engineer