

# FIELD INSPECTION REPORT

Date of Inspection :	05-12-2020	District:	Darbhanga
Division :	Banipur	Length (km):	1.34
Name of the Road:	TOS to Aorauli BR-10R-067		
Scheme/Programme:	MAINTENANCE 8 yrs		
Package No.:	BR-10R-067	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	✓

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

05/12/2020

NAME: Md. Azam Ansari

DESIGNATION: S-B Alduagan

05/12/2020  
A. B. Alduagan

(Signature)