

# FIELD INSPECTION REPORT

|                                 |                                                                                                                      |                                                |         |
|---------------------------------|----------------------------------------------------------------------------------------------------------------------|------------------------------------------------|---------|
| Date of Inspection : 15.12.2020 |                                                                                                                      | District : GAYA                                |         |
| Division : Neemchak Bathani     |                                                                                                                      | Length (Km.) : 0.670 km                        |         |
| Scheme/Programme:               |                                                                                                                      | MAINTENANCE L053 manpur teusa Rd to Bhudhai/la |         |
| Package No. : BR-12-R-756       |                                                                                                                      | Road Id No. :                                  |         |
| Status of the Project :         |                                                                                                                      | Ongoing/Completed/Under Maintenance            |         |
| Work is a case of :             |                                                                                                                      | New Connectivity/Up gradation/Maintenance      |         |
| Sl. No.                         | Parameters to be checked                                                                                             |                                                | Remarks |
| 1                               | Pavement                                                                                                             |                                                |         |
| a)                              | Road Junction condition                                                                                              | S                                              | S/U     |
| b)                              | Condition of Surfacing                                                                                               | U                                              | S/U     |
| c)                              | Riding Quality                                                                                                       | U                                              | S/U     |
| d)                              | Road Camber                                                                                                          | S                                              | S/U     |
| e)                              | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | NA                                             | Yes/No  |
| f)                              | Contraction Joints provided or not (CC Pavement)                                                                     | NA                                             | Yes/No  |
| g)                              | Compaction of flank/slope & raincuts if any                                                                          | yes                                            | Yes/No  |
| 2                               | Cross Drainage                                                                                                       |                                                |         |
| a)                              | Condition of head walls in Hume pipe culverts including its painting                                                 | NA                                             | S/SRI/U |
| b)                              | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | NA                                             | S/SRI/U |
| c)                              | Condition of railings/slab/approach for Bridges                                                                      | NA                                             | S/SRI/U |
| 3                               | Road Furniture                                                                                                       |                                                |         |
| a)                              | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained |                                                | Yes/No  |
| 4                               | Compliance History                                                                                                   |                                                |         |
| a)                              | Status of ATR's & any others.                                                                                        |                                                |         |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | -   |
| Satisfactory but requires improvement (SRI) | SRI |
| Unsatisfactory (U)                          | -   |

Done  
15.12.2020  
J.E