


FIELD INSPECTION REPORT

Date of Inspection : 15-12-20		District : GAYA	
Division : Neemchak Bathani		Length (Km.) : 1.502 km	
Scheme/Programme:		MAINTENANCE Tapwan Nari Bahadur Road to Toz Kachahara	
Package No. : BR-1LR-727		Road Id No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	

Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRI - S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NO Yes/No
4	Compliance History	
a)	Status of ATR's & any others.	NO A.T.R

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 15-12-20