

# FIELD INSPECTION REPORT

Date of Inspection : 15-12-20		District : GAYA	
Division : Neemchak Bathani		Length (Km. : 0-835	
Scheme/Programme:		MAINTENANCE 660 Tapowari Wariv Gaur Road to Toz to Lok Sighani	
Package No. : BR-12R-728		Road Id No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S.R.D.	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A	
c)	Condition of railings/slab/approach for Bridges	N/A	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others.		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S.R.D.
Unsatisfactory (U)	

15-12-20  
S.E.