

FIELD INSPECTION REPORT

Date of Inspection : 15-12-20		District : GAYA	
Division : Neemchak Bathani		Length (Km.) : 1.185 Km.	
Scheme Programme:		MAINTENANCE Loop Chhapra Pakari Road to 27 to Alabail (XPRGJ)	
Package No. :		Road Id No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1 Pavement			
a) Road Junction condition	S	S/U	
b) Condition of Surfacing	S	S/U	
c) Riding Quality	S	S/U	
d) Road Camber	S	S/U	
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes	Yes/No	
f) Contraction Joints provided or not (CC Pavement)	Yes	Yes/No	
g) Compaction of flank/slope & raincuts if any	Yes	Yes/No	
2 Cross Drainage			
a) Condition of head walls in Hume pipe culverts including its painting	SRT -	S/SRT/U	
b) Condition of Abutment & Wing walls, Slab in RCC culverts	N/A	S/SRT/U	
c) Condition of railings/slab/approach for Bridges	N/A	S/SRT/U	
3 Road Furniture			
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
a) Compliance History		Yes/No	
Status of ATR's & any others.			

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

15-12-20
N.E.