

# FIELD INSPECTION REPORT

Date of Inspection : 13.12.2020	District: Yagchi
Division : R.W.D (W) Yagchi	Length (km): 3.658 Km.
Name of the Road: Sanku to Sonai via Ramnik Deem talga	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: 20804103169
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	✓ New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME:

DESIGNATION:

Basal

13/12/2020

(Signature)