## FIELD INSPECTION REPORT

		FISH II		
Date of Inspection: 14.12.20201			District: KATHAR	
Division: To Edrsoi			Length (km): 1.793 km.	
		farpyr se	chouwagochi	
	Programme:	MAINTENANCE	(Maintenace)	
Package	No.: BR-16	R-275	Road Id No.:	
Status of	f the Project:	Ongoing/Complete	ed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance		Remarks
Sl. No.		Parameters	to be checked	
ı.	Pavement			
a)	Road Junction condition			√8/U
Miles w. v.				VSIU
b)	Condition of Surfacing			₩8/U
c)	Riding Quality			S/U
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			VYes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No (
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	The second secon	The second section of the second section of the second sec		Here in
1,000 m	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting			VS/SRI/U
<u>a)</u>	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
b)	Condition of railings/slab/approach for Bridges			S/SRI/U
c)				
3.	Road Furnitu			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Vcs/No
4.	Compliance History			院長 泛道
a)	Status of ATR's & any others			"RI"

Overall Rating :

i e .		
Satisfactory (S)		***
Satisfactory but requ	URI"	
Unsatisfactory (U)		e

(Signature) AE(E

NAME: BHAGIRATH RAM

DESIGNATION: ASSISTANT ENGINEER