FIELD INSPECTION REPORT

(Inches)	
Trispection: 08.19.200 District MacCil Asco	ANT
on: KISHANGANI 2 Length (km)	ANU
of the Road; The AAMBADE ELON MAM	BADI
e/Programme: MAINTENANCE CTCALY	DARI
ge No.: Rond Id No.: 219059180	004
of the Project: Ongoing/Completed/Under Mnintenance	
Parameters to be checked	Remarks
Pavement	
Road Junction condition	87U S
Condition of Surfacing	SAUS
Riding Quality	SAUS
Road Camber	SAY S
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Xes/No No
Contraction Joints provided or not (CC Pavement)	Yes/No Yes
Compaction of flank/slope & raincuts if any	Yes/No-Yes
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	S/SRI/U—
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture	· 在 图
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
Compliance History	是是是
Status of ATR's & any others	
	ge No.: Of the Project: Ongoing/Completed/Under Maintenance is a case of: New Connectivity/Up gradation/ Maintenance Parameters to be cheeked Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of railings/slab/approach for Bridges Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Compliance History

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

NAME: SUNIL KR. RANJAN.

JE/DIGHALBANK-(2).

(Signature) 12.2020