FIELD INSPECTION REPORT

Process of the Proces					
Date o	of Inspection : (0			
Divisi	The state of the s				
Name of the Road: 1000 Total 2010 Length (km): 0.400					
Schem	Scheme/Programme: MAINTENANCE GISNY			398ti	
Package No.: Road Id No.:					
Status of the Project:		Ongoing/Completed/			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No		Parameters to b		Remarks	
1. Pavement					
a)	Road Junction	Road Junction condition			
b)	Condition of Surfacing			S/V/S	
c) Riding Quality				S/V/S	
d)	d) Road Camber			SAYS	
e)		Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)		Yes/No		
g)	Compaction of flank/slope & raincuts if any		f any	Yes/No	
2. Cross Drainage					
a) Condition of hea		nd walls in Hume pipe o	culverts including its painting	S/SRI/U	
b) Condition of A		utment & Wing walls, S	Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		Bridges	S/SRI/U	
3.	Road Furniture				
2) /	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No		
4.	Compliance Histo	pry		EN STATE OF STATE	
Status of ATR's & any others					
The second second second					

Overall Rating

	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	

NAME: SUNIL KR. RANJAN
----J.E./Dighalbank-@