

FIELD INSPECTION REPORT

Date of Inspection : 08.12.2020		District: KISHANGANGJ
Division : KISHANGANGJ-2.		Length (km): 0.250
Name of the Road: 507 SE CHANDBHITTA MUKHIYA TOLA SE ARSAD HUSSAIN GTSNY.		
Scheme/Programme: MAINTENANCE		Road Id No.: 21205918017
Package No.:		
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes.
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No.
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI.
Unsatisfactory (U)	

NAME: SUNIL KR. RANJAN.
JE/ DIGHALBANK-2.

(Signature)

08.12.2020
JE.