

FIELD INSPECTION REPORT

Date of Inspection: 16/12/2020	District: Chittoor
Division: P. W. D. Division	Length (km): 0.5
Name of the Road: P. W. D. Road	
Scheme/Programme: MAINTENANCE	
Package No.:	Head Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	67.5%
Work is a case of: New Connectivity/Up gradation/ Maintenance	
1. Road Condition	
a) Road Junction condition	NI
b) Condition of Surfacing	NI
c) Riding Quality	NI
d) Road Carriway	NI
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f) Construction Joints provided or not (CC Pavement)	Yes/No
g) Composition of Road Slope & retaining if any	Yes/No
2. Culverts/Bridges	
a) Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c) Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture	
a) Whether sign boards/informatory/cautionary Board/km & 200m stone Pavement road markings are provided and maintained	Yes/No
4. Compliance History	
a) Status of ATR's & any others	N/D

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

16.12.20

SE Engineer

16/12/2020

A.E.

Brigadier

NAME:

DESIGNATION: