## FIELD INSPECTION REPORT

Date of Ir	ispection: 15/12/2020	District: myzaffur bur	
Division:	Myzaffarbyr East-2	Length (km): 1.053 km	
	the Road: TO7 to This	hy to Belg.	
	Programme: MAINTENANCI		
Package	No.: BR-23R-439	Rond Id No.:	
		ted/Under Maintenance	
Work is	a case of: New Connectivity	y/Up gradation/ Maintenance	
Sl. No.	Parameters	to be checked	Remarks
1.	Pavement		
a)	Road Junction condition		√S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		√\$ru .
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U -
3.	Road Furniture		D/DIG O
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No=
4.	Compliance History		
a)	Status of ATR's & any others		100
Overall F	Some Posting damas	e ome to overtoping flood u	vater 2020.

Overall Rating

A state of
1 1177

(Signature)

NAME: GAMESH KUMAK

DESIGNATION: JUNEOR EMAJHEER.