

# FIELD INSPECTION REPORT

Date of Inspection :	15-12-2020	District:	West Champaran
Division :	Bagaha-2	Length (km):	BR-37R-572
Name of the Road:	Balahi to Bhagawanpur		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-37R-572	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Under maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	SAU SRL
b)	Condition of Surfacing	SAU SRL
c)	Riding Quality	SAU SRL
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	<b>Cross Drainage</b>	N/A
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Ye
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

*Nagesh Kumar*  
15/12/2020  
(Signature)

NAME: *Nagesh Kumar*  
DESIGNATION: *JE*