FIELD INSPECTION REPORT

spection: 15/12/2020	District: Tgyui	
And the second s	Length (km): 8.450km	
he Road: Tetanine MMP	Road to Joswaha Dharamen	x PMGSY M
rogramme: MAINTENANC	E	
No.:	Road Id No.: 2080410037	25
the Project: Ongoing/Comple	eted/Under Maintenance	
case of: New Connectivi	ty/Up gradation/ Maintenance	Remarks
Parameter	to be checked	Kemarks
Puvement	September 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Company of the Compan	1874 7 PRO SE PAROLIN COLLEGE SERVICES	S/U
		S/U
Condition of Surfacing		S/U
Riding Quality		
Road Camber		_S/U
Whether free from defects	such as visible cracks, exposed	Yes/No N/
aggregates in case of eet dies	not (CC Pavement)	Yes/No N/
		Yes/No A
Compaction of flank/slope & ra	aincuts if any	the state of the s
Cross Drainage		
Condition of head walls in Hur	ne pipe culverts including its painting	S/SRI/U
		SISRIAUNI
		S/SRI/U ~
Walk Told Told Told Told Told Told Told Told		
The state of the s		100
stones/Pavement road marking	s are provided and maintained	Yes/No
Compliance History		
Status of ATR's & any others		NIA
	The Road: Te-tazing PLAP Programme: MAINTENANC No.: the Project: Ongoing/Complete Case of: New Connectivity Parameter Property Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects aggregates in case of CC Paven Contraction Joints provided or Compaction of flank/slope & re Cross Drainage Condition of head walls in Hur Condition of Abutment & Win Condition of railings/slab/appr Road Furniture Whether sign boards/informationes/Pavement road marking Compliance History	Length (km): 8.400km The Road: Tetaling MAINTENANCE No: The Project: Ongoing/Completed/Under Maintenance Parameters to be checked Prement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Cross Drainage Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Firmiture Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Compliance History

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	'U'

To 12/2020

(Signature) A.C

NAME:

DESIGNATION: