FIELD INSPECTION REPORT

			ZARON MINI ON I	
Date of 1	nspection:	12.2020	District: KISHAN	GANJ
Division	KISHA	NICANICO	Length (km): 1.100 KM.	
Name of	the Road:	197 TO 1112	4GIRT	•
Scheme/	Programme:	MAINTENANCE	GTSNY	
Package No.:			Rond Id No.:	
Status of	f the Project:	Ongoing/Completed	/Under Mnintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition S/			S/US
b)	Condition of Surfacing S/U			S/U S
c)	Riding Quality S/J			S/US
d)				SIVS
e)	Whether free from defects such as visible cracks, exposed Yes/No			
f)	Contraction Joints provided or not (CC Pavement) Yes/No			Yes/No Y
g)	Compaction of flank/slope & raincuts if any			Yes/No Y

Condition of head walls in Hume pipe culverts including its painting

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

Condition of railings/slab/approach for Bridges

Overall Rating

g)

2...

a)

b)

c)

3.

a)

a)

Satisfactory (S)	00+
Satisfactory but requires Improvement (SRI)	SKI
Unsatisfactory (U)	

(Signature) 12.2020

S/SRI/U

S/SRI/U

S/SRI/U

NO

NAME: SUNIL KR. RANJAN 12.12.2020

Cross Drainage

Road Furniture

Compliance History

Status of ATR's & any others