## FIELD INSPECTION REPORT

Date o	Inspection:	16.12.2020	District: Sazon	
Name	of the Road: N	Din Marhaura	Length (km): 0.330 [2	M.
- THERE	e/Programme:	IMESY POLL TO	Teli'tola'	
Packag	ge No.:	MAINTENANCE	D- IVIN	
	of the Project:	Ongoing/Completed	Road Id No.: 3130650	1885
	is a case of:	New Connectivity/U	p gradation/ Maintenance	
Sl. No.		Parameters to be checked		Remarks
1,	Pavement .	TO BE A STATE OF		
a)	Road Junction condition			√s/u
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			√Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Ýes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/II			
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
	Road Furniture			
a) _ s	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			√Yes/No
The second second second	Compliance History			
)   S	Status of ATR's & any others			
rall Rai	10000000000000000000000000000000000000	CONTRACTOR OF THE PARTY		NO.

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	5
Unsatisfactory (U)	
Chautsiactory (U)	

(Signature)

NAME: Kansan Ali DESIGNATION: J.6