## FIELD INSPECTION REPORT

Date o	f Inspection:	16/12/20	Di	strict: Kishangan	
Divisio	n: Kist	ranganj-1	Le	ngth(km): 1.00 km.	
Name	of the Road:	PMUSY RO	bad	TO Andhwa Kol Ward	HO-01
Schem	e/Programme:	MAINTENANC	E	( GTS14	
Packag	e No.:			Road Id No.: 2120 580 1814	
			oleted /Under Maintenance		
Work is	s a case of:	New Connectiv	vity/ I	Up gradation / Maintenance	Remarks
\$1. No		Parameters to be checked			
1.	Pavement				LSAU
a)	Road Junction Condition				LS/U
b)	Condition of Surfacing				c8/U
c)	Riding Quality				L8/TU
d)	Road Camber				45/1
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints Provided or not (CC Pavement)				Yes/No
g)	Compaction of fland / shop & raincuts if any				Yes/No
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting				S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts				LS/SRI/U
c)	Condition of railings/Slab/approach for Bridges				LS/SRI/U
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No
4.	Compliance History				
a)	Status of ATR's & any others				NO ATR

Overall Rating :

Satisfactory(S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory(U)

NAME: Bidhayanand frasad AE RWD WOOKB Subdivision Kishangang-L