## FIELD INSPECTION REPORT

Date o	f Inspection:	16/12/20.	District: Kichan 900 m	
Divisio	n: Wishan	9ani - 1	Length(km): Loo Kim.	
Name	of the Road:	PMUSY R	100 Kirs),	10-11
Schem	e/Programme:	MAINTENANCE	oad To Lohadanga.	CATSONY
Packag	e No.:		Road Id No.: 21205801834	
Status of the Project: Ongoing/Completed / Under Maintenance				
Work is	s a case of:	New Connectivi	ty/ Up gradation / Maintenance	
S1. No	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction Condition			18/0
b)	Condition of Surfacing			25/0
c)	Riding Quality			S/U
d)	Road Camber			LS/U
e)				US/U
٠,	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints Provided or not ( CC Pavement)			Yes/No
g)	Compaction of fland / shop & raincuts if any			Yes/No
2.	Cross Drainage			103/110
a)	Condition of head walls in Hume pipe culverts including its Painting			-S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts			S/SRI/U
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U
3.	Road Furniture			6/3KI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's		140	0

Overall Rating:

Satisfactory(S) Satisfactory but requires Improvement (SRI) Unsatisfactory(U)

NAME: Bidnayanand frasad AE, RWD works Subdivision Wishangang