## FIELD INSPECTION REPORT

Date of	Inspection:	16/12/20 District: Kishangany	
Division	1: Kish	angang-1 Length(km): 2.0 Km	
Name o	of the Road:	frangsy Road To Kathmohan,	COTSHY)
Scheme	e/Programme:	MAINTENANCE	
Packag	e No.:	Road Id No.: 2120 580 1843	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is	a case of:	New Cornectivity/ Up gradation / Maintenance	
S1. No		Parameters to be checked	Remarks
1.	Pavement		S/U
a)	Road Junction Condition		SHU
b)	Condition of Surfacing		StU
c)	Riding Quality		~8/U
d)	Road Camber		S/U
e)	Whether free	Yes/No	
	in case of CC P		
f)	Contraction Joints Provided or not (CC Pavement)		Yes/No
g)	Compaction of flan₩/ shop & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m		Yes/No
	stones/Pavem		
4.	Compliance H	listory	
a)	Status of ATR's & any others		NO AT

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: Arnal frakash. EE RWD Kishanganj-1