## FIELD INSPECTION REPORT

			TON KIN OF		,
Date of Inspection: 12.12.2020 District: KISHANGANJ					
Division: KISHANGAN(1-2 Length (km): 0.500					
Name of the Road: LOG3 TO CHHAITPUR PURABTOLA					
Scheme/Programme: MAINTENANCE GTSNY					
Package No.: Rond Id No.:					
Status of the Project:		Ongoing/Completed/Under Mnintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No. Parameters to be cheeked Remarks					
1.	Pavement				
a)	Road Junction condition				SIVS
b)	Condition of Surfacing				SABU
c)	Riding Quality				8/U U
d)	Road Camber				SIVS
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any  Yes/No				Yes/No
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe curvers including his parameter				S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c)	Condition of railings/slab/approach for Bridges				S/SRI/U
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No NO
74.7	Compliance l	listory	位的對於	(2) (1) (1) (1) (1) (1) (1) (1)	等一种 · · · · · · · · · · · · · · · · · · ·
a)	Status of ATR	's & any others	1		
				A STATE OF THE PARTY OF THE PAR	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature) 2020

NAME: SUNIL KR. RANJAN 12.12.2020