

FIELD INSPECTION REPORT

Date of Inspection : 08.12.2020	District: KISHANGANJ
Division : KISHANGANJ-2.	Length (km): 0.100
Name of the Road: 507 TARABARI SE MUKHIYA TOLA CHANDBHITA SE NAYABASTI	
Scheme/Programme: MAINTENANCE	GTSNY.
Package No.:	Road Id No.: 21205901897
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes.
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

SUNIL KR. RANJAN.
08.012.2020

(Signature)

08.12.2020
JE