

# FIELD INSPECTION REPORT

Date of Inspection : 9/12/2020		District: muzaffarpur
Division : muzaffarpur East-2		Length (km): 0.850 km
Name of the Road: Tripti Sahni house to purab nadi tak		
Scheme/Programme: MAINTENANCE		mmusy
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Some portion of flank damage due to flood water 2020.

NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	" SRI "
Unsatisfactory (U)	

Ganesh Kumar

9/12/2020

(Signature)

NAME: GANESH KUMAR

DESIGNATION: Junior Engineer.