

FIELD INSPECTION REPORT

Date of Inspection : 11.12.20	District: GAYA
Division : RWD, TEKARI	Length (km): 1.5 km
Name of the Road: DIHURI TO L28	
Scheme/Programme: MAINTENANCE	Maintenance -
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Completed
Work is a case of: New Connectivity/Up gradation/ Maintenance	New Connectivity

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: Avinash Kumar

(Signature)
A.E. (RWD) (W) Div. Tekari
11/12/20