

FIELD INSPECTION REPORT

Date of Inspection :	15.12.2020	District:	Purnea
Division :	Baide	Length (km):	1.705
Name of the Road:	Mahtaur Mushari PMGSY to Rahmatnagar		
Scheme/Programme:	MAINTENANCE	Road Id No.:	MMGSY
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	S
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	Yes/No	Yes
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	S
c)	Condition of railings/slab/approach for Bridges	S/SR/U	S
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Binod
(Signature)

NAME: R. B. Singh

DESIGNATION: D. J. E