

FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020		District : E. Champarn	
Division : Chakia		Length (Km):	
Name of the Road : Baranea to 1021 (GTSNY)			
Scheme/Programme :		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1,	Pavement		
a)	Road Junction condition	'S'	
b)	Condition of Surfacing	'S'	
c)	Riding Quality	-	
d)	Road Camber	'S'	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	'S'	
f)	Contraction Joints provided or not (CC Pavement)	'S'	
g)	Compaction of flank/slope & raincuts if any	-	
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	'S'	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-	
c)	Condition of railings/slab/approach for Bridges	-	
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	U	
4,	Compliance History		
a)	Status of ATR's & any others	-	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	SRI
	Unsatisfactory (U)	

Note :- Road Furniture are not sufficient and 200m are not properly fixed at site

NAME :

DESIGNATION :

[Signature]
16.12.20
J.E

(Signature)