FIELD INSPECTION REPORT

Date of		5/12/20	District: al. Champara	
Divisio	1100 Virginia	a AgnT	Length (km): D. 8 10 10	n
	ittie Road:	of to Solia to	Bhangaha Parsaund	190 Km
	/Programme:	MAINTENANCE		
Packag	011	ZNY	Road Id No.: 31808901	0//
The state of the s			interence	
Work i	s a case of:	New Connectivity/U	p gradation/ Maintenance	uncerence
Sl. No.		Parameters to be checked		Remarks
1.	Pavement			
a)	Road Junction	ς		
b)	Condition of Surfacing			5
c)	Riding Quality			5
d)	Road Camber			S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			S
Ŋ	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			¥ -
2.	Cross Drainag	je		
a)	Condition of head walls in Hume pipe culverts including its painting			
b) -	Condition of Abutment & Wing walls, Slab in RCC culverts			_
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furniture			
а)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			S
4.	Compliance History			
a) (Status of ATR's & any others			

Overall Rating

Satisfactory (S)	<i>'</i>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	_

(Signature)

NAME: Chandrales Pd DESIGNATION: JE