FIELD INSPECTION REPORT

GIJJNY

Date o	f Inspection: 12	112.2020	District: W. Champaran	
Division: Narkatia gand Length (km): 0, 500 km				
	of the Road: 77	of to marjad	lucy Balizampin	
	c/Programme:	MAINTENANCE	•	
Packag		NY	Road Id No.: 3/8089018	91
	of the Project:	Ongoing/Completed	Under Maintenance Under me	interence
<u></u>	s a case of:	THE RESERVE OF THE PARTY OF THE	p gradation/ Maintenance LTS	NY
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			ی
b)	Condition of Surfacing			S
c)	Riding Quality		2	
d)	Road Camber		S	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S	
f)	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			-
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		_	
c)	Condition of railings/slab/approach for Bridges			_
3.	Road Furnitui	re	to the statement of the	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			is.
4.	Compliance Hi	story		A state
a)	Status of ATR's & any others			-

Overall Rating

Satisfactory (S)	5'
Satisfactory but requires Improvement (SRI)	10 m
Unsatisfactory (U)	

12/12/20 (Signature)

NAME: Chandrades Pel

designation: $j \epsilon$