

PMU 2024.

FIELD INSPECTION REPORT

Date of Inspection :	14/12/2020	District:	PATNA
Division :	BAPU	Length (km):	3.347
Name of the Road:	Prachadpur to Chakrampura		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-262-201	Road Id No.:	
Status of the Project:	Ongoing Completed Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		PMUSY

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls Slab in RCC culverts	S/SRI/U
c)	Condition of railings slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/4m & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	ATR

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	U

Bhumer
14/12/20
(Signature)

NAME: BINOD KUMAR
JUNIOR ENGINEER