

NABARD.

FIELD INSPECTION REPORT

Date of Inspection : 13-12-2020	District: Sonpur
Division : Sonpur	Length (km): 3.2 Km
Name of the Road: Kobbharha Jhagha PWD Road to Assuta Bank to	
Scheme/Programme: MAINTENANCE	Karanpur
Package No.: N.A	Road Id No.: 20804100327
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	SAT
b)	Condition of Surfacing	SAT
c)	Riding Quality	SAT
d)	Road Camber	SAT
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:

(Signature)



AE, Laxmipur