FIELD INSPECTION REPORT

Date of la	spection: 13-	12-2020	District: Jem		
Division: Jamui			Length (km): 0 - 8	37	Kon
Name of t		7- 701 7	Buswan Tok		
		AINTENANCE	and the second second		
Package I			Road Id No.: 2080-	4100	205
			/Under Maintenance		
		Jp gradation/ Maintenance			
Sl. No.		Parameters to	be checked	ing or skying January	Remarks
1	Pavement	A cast and set findings	rii. W. Junjandiesche State C. L.	24 - 1505	erio de la como de la
a)	Road Junction condition				SÆ
b)	Condition of Surfacing				SAU
c)	Riding Quality				SÆ
d)	Road Camber				SÆ
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any				Xes/No
1. 2.	Cross Drainage			v 4,548	
a)	Condition of head walls in Hume pipe culverts including its painting				-S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges				S/ SRI/U
3	Road Fuiniture	A part de			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes /No
4.	Complinate History				g) makandengg 2
a)	Status of ATR's & any others				N/A

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

John Shippons

(Signature)

NAME:

DESIGNATION: