

FIELD INSPECTION REPORT



Date of Inspection :	12/12/2020	District:	Jamui
Division :	Jamui	Length (km):	1.795
Name of the Road:	L/34 - T01 Road To Orba/ev		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	20804100208
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	. SAU	
b)	Condition of Surfacing	SAU	
c)	Riding Quality	SAU	
d)	Road Camber	SAU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/SAU	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/SAU	
c)	Condition of railings/slab/approach for Bridges	S/SRI/SAU	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:

 12/12/20
 AE, Laxmipura

(Signature)