FIELD INSPECTION REPORT

		FIELD HASTE	TION REPORT		
Date of 1	Inspection:	3-12-2020	District: Whas		
Division	1 - 10 10 00			4	
Name of		Bhoothalk Rea	D 9 9		
Scheme	Programme:	MAINTENANCE		0.11	
Package	No.:	1	Road Id No.: 21205901	816	
Status o	f the Project:	Ongoing/Completed	/Under Mnintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance Remarks			
Sl. No.		Parameters to	be checked		
1.	Pavement			C/II	
a)	Road Junction condition			S/U <	
				S/U - 9	
b)	Condition of Surfacing			S/U -S	
c)	Riding Quality			S/U -S	
d)	Road Camber			Yes/No -	
e)	Whether free from detects such as				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
	Compaction of flank/slope & raincuts if any Y			Yes/No	
g)	· · · · · · · · · · · · · · · · · · ·				
2	Cross Draina	ge and taken	a trialuding its painting	S/SRI/U -	
a)	Condition of head walls in Hume pipe culverts including its pariting			C/SBI/II	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridges S/SR			s/srl/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance History				
於自由的學生	Status of ATR	's & any others		No	
a)	Dunius Of 11111				

Overall Rating

Satisfactory (S)	001
Satisfactory but requires Improvement (SRI)	SKI
Unsatisfactory (U)	

(Signature)

NAME:

Conned by Com Conne